
User Manual

Cautions

- Upon receiving the scale, please take at least 8 hours to recharge the battery before you start to operate this scale.
- Please recharge the battery after a long period of storage (more than one month). It takes 8~10 hours to fully recharge the battery.
- Please assemble the platter before powering on the scale.
- Do not keep the weight placed on the platter for a long period.
- Keep the scale away from the environment with high temperature \ high humidity \ heavy press \ heavy bump.
- Always make sure the scale is located in a flat and plane surface.

Panel

The below panel is suitable for table scale/indicator/ bench scale/ floor scale.



Installation Diagram of Bench Scale: please see page 8

Symbols on LCD

■ Zero Symbol (*o*):

O appears on the left-bottom corner of LCD, and indicates the scale is at zero-point.

■ NET Weight Symbol (Net):

Net appears on the bottom edge of LCD, and indicates the tare weight has been deducted.

Battery Symbol (+-):

When LCD indicates +- and the scale sounds **beep for four times.** It means the battery is running in low-voltage status. LCD will indicate +- continuously for reminding the user to recharge the battery. If the battery is still running in low-voltage status without being recharged, LCD with indicate **-OFF-** and the scale with sound **beep for eight times**. Please power off the scale and recharge the battery immediately.

■ Indication of Weighing Range (**▼**):

- ▼ Cursor appears on the bottom edge of LCD (above of W1 or W2 printed on the display-overlay), and indicates the present weighing range to be Weighing Range 1 (W1) or Weighing Range 2 (W2).
- **!!** Notice: The indication of weighing range is only available for the scale / indicator with multiple range (2 ranges).

Operation Instructions

■ **Backlight** (optional):

Press and hold $\rightarrow 0$ key till the scale sounds **beep** to enable / disable the Backlight.

UNIT:

Select the weight mode: kg / pcs.

■ Under **pcs** (simple counting) mode:

- !! The suggested unit weight of the measured subject should be heavier than the division of this scale.
- 1. Put 100 pieces of the measured subject (with the same unit weight) on the platter.
- Press and hold [UNIT] key till LCD shows S= 10, and then quickly (within 3 seconds) press [UNIT] key again to select S=100 (10 \ 20 \ 50 \ 100 could be selected for the sample-quantity of the measured subject).
- 3. Wait till LCD shows **100**. The scale has finish calculating the averaging unit weight of the measured subject. Now the simple counting function is ready. This scale could be used as a simple counting scale.


Press this key to make the scale be at zero point. LCD will indicate **O** on the left-bottom corner.

Press this key to deduct the tare weight. Put the package or container on the platter and then press [*TARE*] key. LCD will show *O* and *Net*.

■ PRINT:

- 1. Press this key to send out weighing data to printer when equip with RS232 Interface.
- 2. Press this key will sound "beep beep" alarm when not equip with Printer Device.

RS232 Interface Connection: < optional device>



RS232 Wiring Configuration:

Baurate: 9600

Parity: None

Stop Bit: 1

Data Bit: 8

Recharge 1	the Battery	
-------------------	-------------	--

Power off the scale and connect the power cord to an AC outlet. *CHARGE LED:* will indicate the ongoing status of the battery. It takes about *8~10 hours* to fully recharge the battery.

CHARGE LED:

Color of LED	Status of the battery
RED	Initial connection
ORANGE	Charging
GREEN	Fully-charged

Power Requirements

● AC: 220V±10%, 50Hz

DC: 6V/4Ah rechargeable battery;

P=0.2W(max)

Installation Diagram of Bench Scale

List	of Components:			1/28
No.	Item		(<u> </u>
<1>	Indicator			2
<2>	Bracket			
<3>	Stainless Steel Tube			
<4>	Tube Base			
<5>	Stainless Steel Platter			
<6>	Main Structure			3
<7>	Cable of Load Cell	5		\Box
<8>	Connector	ė	F	∮
		6		4

Installation Procedure:

- A. Screw <4> Tube Base and <6> Main Structure together (with 2 screws of Tube Base).
- B. Insert <3> Stainless Steel Tube into <4> Tube Base (with 2 screws of Stainless Steel Tube).
- C. Screw <2>Regulator and <3> Stainless Steel Tube together (with 1 screw and 1 clip of Regulator).
- D. Please refer to the Diagram; pull <7> Cable of Load Cell, from the bottom to the top, through <3> Stainless Steel Tube; and then screw the Clip on the bottom of <4> Tube Base (with 1 screw of Clip).
- E. Connect <1> Indicator with <2> Regulator. Notice the direction. Please refer to the arrow on the diagram for proper direction.
- F. Put <5> Platter on <6> Main Structure.
- G. Insert <8>Connector into the socket of <1>Indicator. Complete installation

<u>**Before using this scale, please unscrew the protecting-screw fixed on the bottom side of the steel-welding base structure.</u>

NOTE:	

NOTE :		

