

# User Manual

---

**AW/DW** Series

***DIGITAL WEIGHING SCALE***

## Cautions

---

- When LCD shows “-----”, it means OVERLOAD. Please remove the measured objects away from the platter immediately.
- Please assemble the platter before powering on the scale.
- Do not keep the weight placed on the platter for a long period.
- Keep the scale away from environments with high temperatures, high humidity, heavy pressure, or heavy jarring.
- Make sure the scale is located on a flat and plane surface.

## Dimensions

---

- Scale Body:185 x 225 x 80 (mm)
- Platter:143 x 150 (mm)

## Symbols on LCD \_\_\_\_\_


### ■ Zero Symbol →0←

→0← appears on the left-bottom corner of LCD, and indicates the scale is at zero-point.

### ■ Tare Weight Symbol ←T

←T appears on the bottom edge of LCD, and indicates the tare weight has been deducted.

### ■ Battery Symbol

 appears on the bottom edge of LCD, and indicates the battery is running in low-voltage status. This is for reminding the user to change the battery as soon as possible.

## Operation Instructions \_\_\_\_\_


### ■ ON/OFF :

Turn on or off the scale.




### ■ UNIT :

Select the weighing mode (**g** / **lb** / **oz** / **pcs**).

## ■ TARE/ZERO:

1. Pressing this key to zero the weight that is lighter than the division. LCD will indicate →0←.
2. When the measured weight is heavier than the division, pressing this key will give the net weight. Place a package or container on the platter and press this key to deduct the tare weight, LCD will indicate →0←  and **0.000**

## ■ NET/GROSS:

1. Put the container or package on the platter, and then press [**TARE/ZERO**] key. LCD will indicate **0.000** and . At this moment, pressing [**NET/GROSS**] key once will recall the deducted tare weight of container or package. Pressing [**NET/GROSS**] key again, LCD will indicate →0←  and **0.000** again.
2. Put the container or package on the platter and then press [**TARE/ZERO**] key. LCD will indicate →0←  and **0.000**. Then put the measured subject into the container or package. LCD will indicate the **Net Weight Value**. At this moment, pressing [**NET/GROSS**] key once will obtain the total **Gross Weight Value**. Pressing [**NET/GROSS**] key again, LCD will go back to the **Net Weight Value** again.

## Particular Setup Functions \_\_\_\_\_

### ■ Setting the Auto-Off Feature

1. Press and hold [NET/GROSS] key for 2 seconds till the scale sounds beep, then the Weigh LCD will indicate -2- or -5- or -15- or -30 or -OFF-.
2. Select the auto-off setting time (Minutes)

Press [UNIT] key once to select -2- or -5- or -15- or -30 minutes or -OFF-.

3. Press [NET/GROSS] key to confirm the auto-off setting. Then LCD will indicate **0.000**.

### ■ Backlight (optional)

1. Press [TARE/ZERO] key for 2 seconds till the scale sounds beep to enable or disable the Backlight.

### ■ Setting the Quantity

Under **pcs** (simple counting) mode:

**!!** The suggested unit weight of the measured subject should be heavier than ***the division of this scale***.

1. Put 100 pieces of the measured subject (with the same unit weight) on the platter.

2. Press and hold [**UNIT**] key till LCD shows **S= 10**, and then quickly (within 3 seconds) press [**UNIT**] key again to select **S=100** (10、20、50、100、200 could be selected for the sample-quantity of the measured subject).
3. Wait till LCD shows **100**. The scale has finish calculating the averaging unit weight of the measured subject. Now the simple counting function is ready. This scale could be used as a simple counting scale.

## Power Supply \_\_\_\_\_

### ■ AW Power Source:

DC: 2.2Ah/3.7V Lithium Battery

AC: 110V/220V  $\pm$  10%, 50/60Hz

### ■ DW Power Source:

DC: 1.5V Size AA Dry Battery\*4pcs

AC: 110V/220V  $\pm$  10%, 50/60Hz

# Calibration Instructions

---

Please power off the scale before operating the following procedures.

1. Turn on the scale, press and hold [**NET**] key; do not release your fingers until LCD is showed *the version (7.2)*.
2. Press [**UNIT**] key for 2 seconds, then LCD will be showed **SETUP**.
3. Press [**NET**] key once to enter Calibration Mode, LCD will flash CAL-1, and then showed 00.000
4. Press [**TARE**] key to shift flashing digit.  
Press [**UNIT**] key to modify the flashing digit.  
Then press [**NET**] key to confirm and wait till LCD shows 0.

**\*\*Example:**

If you use 1kg standard weight to calibrate the scale, press [**TARE**] key to shift flashing digit to 00.000 and press [**UNIT**] key to modify the flashing digit to 00**1**.000, then press [**NET**] key to confirm and wait till LCD shows 0.

6. Put the standard weight on the platter and press [**NET**] to confirm, the scale will flash "**good**" and save data after stability. The scale will restart automatically.

